

A80 Supra GR Heritage Parts List

2022/4/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.
 ※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
1	69210-14110- **	69210-14130	HANDLE ASSY, FR DOOR OUTSIDE, RH	All	1	
2	69220-14110- **	69220-14140	HANDLE ASSY, FR DOOR OUTSIDE, LH	All	1	
3	44610-14860, 44610-14880, 44610-1B010	44610-14860	BOOSTER ASSY, BRAKE	USA(part of) EUR (LHD) GEN (LHD)	1	
4	81130-1B160, 81130-1B250	81130-1B160	HEADLAMP UNIT ASSY, RH	Early model(Japan)	1	
5	81170-1B160, 81170-1B250	81170-1B160	HEADLAMP UNIT ASSY, LH	Early model(Japan)	1	
6	89465-19635	89465-19635	SENSOR, OXYGEN	Turbo early model(Japan)	1	
7	89465-19725	89465-19725	SENSOR, OXYGEN	Turbo early model(Japan)	1	
8	52119-14918 52119-14916	52119-14420	COVER, FR BUMPER L/COLOR	Japan early model European model	1	Drilling holes to a bumper is necessary.
9	52119-14927	52119-14430	COVER, FR BUMPER L/COLOR	Japan late model	1	Drilling holes to a bumper is necessary.
10	52119-14917	52119-14440	COVER, FR BUMPER L/COLOR	US early model	1	Drilling holes to a bumper is necessary.
11	69005-14750	69005-14750	CYLINDER & KEY SET	USA model (1996.07-1997.09) (Note)There is the compatibility with all models but some changes will happen to your vehicle. Please see the following note.	1	<ul style="list-style-type: none"> •(Note) It is also possible to replace the other USA models, JPN models and EUR models. At that time, if the vehicle is equipped with ignition key lighting, it will not be lit. • The key number will be a new number. • The following items are included in this set. (3 keys, ignition switch lock cylinder assembly, front door lock cylinder assembly RH, front door lock cylinder assembly LH, glove compartment door lock cylinder assembly and luggage compartment door lock cylinder ASSY) •Purchase of separate cylinders is not available. • When replacing the luggage compartment door lock cylinder assembly It may not be possible to connect the connector on some vehicles with US specifications. In that case, please replace it according to the following procedure. 1) Remove the cylinder side connector attached to the vehicle. 2) Remove the cylinder side connector of the reprinted product and replace it with the connector removed in (1). 3) Connect to the connector on the vehicle side. If it is not connected to the connector on the vehicle side, security may sound when the door is unlocked.

■ Substitute Parts(Genuine)

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
11	44610-14850 44610-14870	44610-14850	BOOSTER ASSY, BRAKE	USA(part of) EUR (RHD) GEN (RHD) JPN(part of)	1	44610-14870 was substituted by this part due to fitment has been confirmed.
12	44610-14890	44610-14890	BOOSTER ASSY, BRAKE	JPN(part of)	1	This part has been continuously supplied, not revival parts.

A80 Supra GR Heritage Parts List

2022/4/1

■ Substitute Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.
※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
13	81111-1B230 81111-1B231	81111-1B231	HEADLAMP UNIT ASSY, RH	Late model(Japan)	1	81111-1B230 was substituted by this part due to fitment has been confirmed.
14	81151-1B230 81151-1B231	81151-1B231	HEADLAMP UNIT ASSY, LH	Late model(Japan)	1	81151-1B230 was substituted by this part due to fitment has been confirmed.
15	48610-19025	48610-29046	ARM ASSY SUSPENSION, RH	All models (1993.05-1996.05)	1	48610-19025 was substituted by this part due to fitment has been confirmed.
16	48630-19025	48630-29046	ARM ASSY SUSPENSION, LH	All models (1993.05-1996.05)	1	48630-19025 was substituted by this part due to fitment has been confirmed.