

A80 Supra Revival and Substitute Parts

As of April 1st 2021

No.	Model	Original Part Number	Current Part Number	Part Name	Vehicle application	Part type	Quantity per unit	Note
1	A80Supra	69210-14110-**	69210-14130	HANDLE ASSY, FR DOOR OUTSIDE, RH	All	Revival Parts	1	
2	A80Supra	69220-14110-**	69220-14140	HANDLE ASSY, FR DOOR OUTSIDE, LH	All	Revival Parts	1	
3	A80Supra	44610-14860, 44610-14880, 44610-1B010	44610-14860	BOOSTER ASSY, BRAKE	USA(part of) EUR (LHD) GEN (LHD)	Revival Parts	1	
4	A80Supra	44610-14850, 44610-14870	44610-14850	BOOSTER ASSY, BRAKE	USA(part of) EUR (RHD) GEN (RHD) JPN(part of)	Substitute Parts	1	44610-14870 was substituted by this part due to fitment has been confirmed.
5	A80Supra	44610-14890	44610-14890	BOOSTER ASSY, BRAKE	JPN(part of)	Genuine Parts	1	This part has been continuously supplied, not revival parts.
6	A80Supra	81130-1B160, 81130-1B250	81130-1B160	HEADLAMP UNIT ASSY, RH	Early model(Japan)	Revival Parts	1	
7	A80Supra	81170-1B160, 81170-1B250	81170-1B160	HEADLAMP UNIT ASSY, LH	Early model(Japan)	Revival Parts	1	
8	A80Supra	81111-1B230, 81111-1B231	81111-1B231	HEADLAMP UNIT ASSY, RH	Late model(Japan)	Substitute Parts	1	81111-1B230 was substituted by this part due to fitment has been confirmed.
9	A80Supra	81151-1B230, 81151-1B231	81151-1B231	HEADLAMP UNIT ASSY, LH	Late model(Japan)	Substitute Parts	1	81151-1B230 was substituted by this part due to fitment has been confirmed.