

# A80 Supra GR Heritage Parts List

2023/11/1

## ■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.  
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.  
 ※You can check the image of the parts from our HP.

| No. | Original Part Number                        | Current Part Number | Part Name                           | Vehicle Application   | Quantity per Unit | Note  |
|-----|---|---------------------|-------------------------------------|---|-------------------|---|
| 1   | 69210-14110-**                              | 69210-14130         | HANDLE ASSY, FR DOOR OUTSIDE, RH    | All   | 1                 |   |
| 2   | 69220-14110-**                              | 69220-14140         | HANDLE ASSY, FR DOOR OUTSIDE, LH    | All   | 1                 |   |
| 3   | 44610-14860,<br>44610-14880,<br>44610-1B010 | 44610-14860         | BOOSTER ASSY, BRAKE                 | part of USA model<br>EUR model (LHD)<br>GEN model (LHD)   | 1                 | USA model non-turbo   |
| 4   | 81130-1B160,<br>81130-1B250                 | 81130-1B160         | HEADLAMP UNIT ASSY, RH              | Early model(Japan)  | 1                 |   |
| 5   | 81170-1B160,<br>81170-1B250                 | 81170-1B160         | HEADLAMP UNIT ASSY, LH              | Early model(Japan)  | 1                 |   |
| 6   | 89465-19635                                 | 89465-19635         | SENSOR, OXYGEN                      | Turbo early model(Japan)  | 1                 |   |
| 7   | 89465-19725                                 | 89465-19725         | SENSOR, OXYGEN                      | Turbo early model(Japan)  | 1                 |   |
| 8   | 52119-14918<br>52119-14916                  | 52119-14420         | COVER, FR BUMPER L/COLOR            | Japan early model<br>European model   | 1                 | Drilling holes to a bumper is necessary.  |
| 9   | 52119-14927                                 | 52119-14430         | COVER, FR BUMPER L/COLOR            | Japan late model  | 1                 | Drilling holes to a bumper is necessary.  |
| 10  | 52119-14917                                 | 52119-14440         | COVER, FR BUMPER L/COLOR            | US early model  | 1                 | Drilling holes to a bumper is necessary.  |
| 11  | 69570-14060<br>69570-14070                  | 69570-14070         | CYLINDER ASSY, IGNITION SWITCH LOCK | JPN model   | 1                 | <ul style="list-style-type: none"> <li>•In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase.</li> <li>•Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.</li> </ul>   |
| 12  | 69005-14750                                 | 69005-14750         | CYLINDER & KEY SET                  | USA model<br>(1996.07-1997.09)<br><br>(Note)There is the compatibility with all models but some changes will happen to your vehicle. Please see the following note. | 1                 | <ul style="list-style-type: none"> <li>•(Note) It is also possible to replace the other USA models, JPN models and EUR models. At that time, if the vehicle is equipped with ignition key lighting, it will not be lit.</li> <li>• The key number will be a new number.</li> <li>• The following items are included in this set. (3 keys, ignition switch lock cylinder assembly, front door lock cylinder assembly RH, front door lock cylinder assembly LH, glove compartment door lock cylinder assembly and luggage compartment door lock cylinder ASSY)</li> <li>•Purchase of separate cylinders is not available.</li> <li>• When replacing the luggage compartment door lock cylinder assembly<br/>It may not be possible to connect the connector on some vehicles with US specifications.<br/>In that case, please replace it according to the following procedure.<br/>1) Remove the cylinder side connector attached to the vehicle.<br/>2) Remove the cylinder side connector of the reprinted product and replace it with the connector removed in (1).<br/>3) Connect to the connector on the vehicle side.<br/>If it is not connected to the connector on the vehicle side, security may sound when the door is unlocked.</li> </ul> |
| 13  | 69510-14110                                 | 69510-14110         | CYLINDER ASSY, FR DOOR LOCK, RH     | JPN model   | 1                 | <ul style="list-style-type: none"> <li>•In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase.</li> <li>•Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.</li> </ul>   |

# A80 Supra GR Heritage Parts List

2023/11/1

## ■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.  
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.  
 ※You can check the image of the parts from our HP.

| No. | Original Part Number | Current Part Number | Part Name                       | Vehicle Application   | Quantity per Unit | Note  |
|-----|----------------------|---------------------|---------------------------------|---|-------------------|---|
| 14  | 69520-14100          | 69520-14100         | CYLINDER ASSY, FR DOOR LOCK, LH | JPN model   | 1                 | <ul style="list-style-type: none"> <li>•In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase.</li> <li>•Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.</li> </ul> |
| 15  | 68131-14320          | 68131-14320         | GLASS, BACK DOOR                | USA model (1996.07-1998.08)<br>Due to the different printed antenna pattern, it cannot be used in Japan. Japan model is currently supplied as 68131-14300-76 (as of June 2023). | 1                 | <ul style="list-style-type: none"> <li>•The background color is shown in the product image, but the glass color is green.</li> <li>•As the part number differs depending on the destination, please purchase 68131-14320 when purchasing overseas, and 68131-14320-76 when purchasing in Japan.</li> </ul>                                  |
| 16  | 84140-20540          | 84140-20540         | SWITCH ASSY, HEADLAMP DIMMER    | JPN model (1997.09-2002.08)   | 1                 |   |
| 17  | 44771-14010          | 44771-14010         | HOSE, VACUUM TUBE CONNECTOR     | JPN model<br>EUR model RHD  | 1                 |   |
| 18  | 44774-14100          | 44774-14100         | HOSE, UNION TO CONNECTOR TUBE   | JPN model Turbo<br>EUR model RHD  | 1                 |   |

## ■ Substitute Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.  
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.  
 ※You can check the image of the parts from our HP.

| No. | Original Part Number       | Current Part Number | Part Name               | Vehicle Application  | Quantity per Unit | Note   |
|-----|----------------------------|---------------------|-------------------------|--|-------------------|--|
| 1   | 44610-14850<br>44610-14870 | 44610-14850         | BOOSTER ASSY, BRAKE     | part of USA model<br>EUR model (RHD)<br>GEN model (RHD)<br>part of JPN model | 1                 | <p>44610-14870 was substituted by this part due to fitment has been confirmed.</p> <p>USA model turbo<br/>JPN model (tire size)<br/>front 225/50ZR16 + rear 225/50ZR16<br/>front 225/50ZR16 + rear 245/50ZR16<br/>front 225/50ZR16 + rear 245/45ZR16<br/>front 235/45ZR17 + rear 255/40ZR17 (-1996.05)</p> |
| 2   | 44610-14890                | 44610-14890         | BOOSTER ASSY, BRAKE     | part of JPN model  | 1                 | <p>This part has been continuously supplied, not revival parts.</p> <p>JPN model (tire size)<br/>front 235/45ZR17 + rear 255/40ZR17 (1996.05-)</p>   |
| 3   | 81111-1B230<br>81111-1B231 | 81111-1B231         | HEADLAMP UNIT ASSY, RH  | Late model(Japan)  | 1                 | 81111-1B230 was substituted by this part due to fitment has been confirmed.  |
| 4   | 81151-1B230<br>81151-1B231 | 81151-1B231         | HEADLAMP UNIT ASSY, LH  | Late model(Japan)  | 1                 | 81151-1B230 was substituted by this part due to fitment has been confirmed.  |
| 5   | 48610-19025                | 48610-29046         | ARM ASSY SUSPENSION, RH | All models (1993.05-1996.05)   | 1                 | 48610-19025 was substituted by this part due to fitment has been confirmed.  |
| 6   | 48630-19025                | 48630-29046         | ARM ASSY SUSPENSION, LH | All models (1993.05-1996.05)   | 1                 | 48630-19025 was substituted by this part due to fitment has been confirmed.  |